


CSI 6300 SIS – Firmware Update



Dear Valued Customer,

To increase the availability of our CSI 6300 SIS Overspeed Protection System we developed a new firmware version for our A6370D and A6370D/DP modules.

This firmware update includes fixing of minor bugs and providing extended configuration options to the modules, which end up in a higher availability of the overall CSI 6300 SIS system. This update is no fix to any safety related issue.

This module already comes with the latest firmware available.



The firmware version V1.04 of this module is not compatible to earlier version V1.02

It's mandatory to update all modules within the overall CSI 6300 SIS system to the latest firmware V1.04 to ensure proper function and remain a SIL certified system.

Please contact our Customer Support for more information on firmware compatibility and how to update your existing modules to the latest firmware.

Yours sincerely,

Bjoern Mueller

Product Manager Online Systems & Sensors

Reliability Solutions

©2017, Emerson. All rights reserved.

The Emerson logo is a trademark and service mark of Emerson Electric Co. All other marks are the property of their respective owners.

The contents of this publication are presented for informational purposes only, and while every effort has been made to ensure their accuracy, they are not to be construed as warranties or guarantees, express or implied, regarding the products or services described herein or their use or applicability. All sales are governed by our terms and conditions, which are available on request. We reserve the right to modify or improve the designs or specifications of our products at any time without notice.

Emerson
Reliability Solutions
835 Innovation Drive
Knoxville, TN 37932 USA
☎ +1 865 675 2400

🌐 www.emerson.com/ams